AMENDMENTS TO THE SPECIFICATION

IN THE SPECIFICATION:

Please amend paragraph [0091] as follows:

When the cam lobe slides over (contacts) the roller 92, the inner lever $\frac{96}{86}$ dips into the valve lever 72 so that the cam lobe is inactive (i.e., the valve 70 is not actuated).